



WIRE CHUCKS ★ short sort




Chuck 4,5




Chuck 6



Chuck 6,5



Chuck 8




Chuck 10

to be used with:	Dia of shank	Total length	Bored $\frac{1}{10}$ mm	Price Fr.
Small drilling-, milling-machines.	4,5	22,6	4-40	1.80
Lathes Lorch, Boley, Wolf- Jahn, automatic machines Tornos, Petermann etc.	6	31	4-50	1.80
Lathes Lorch, Boley, Wolf-Jahn etc.	6,5	31	4-50	1.80
Lathes Boley, Wolf-Jahn, Lorch, automatic machines Tornos, Petermann etc.	8	35	4-74	1.90
Lathes Schaublin, Wolf-Jahn, Dixi etc.	10	43	4-90	2.80







CH. SCHÄUBLIN-VILLENEUVE, MALLERAY (Switzerland)




Chuck 12



Chuck 15




Chuck 15 B




Chuck 20


to be used with:	Dia of shank	Total length	Bored $\frac{1}{10}$ mm	Price Fr.
Lathes Waltham Dixi, Wolf-Jahn Schaublin etc.	12	46	4—100	3.30
Lathes Waltham	15	58,5	4—130	4.-
Lathes Dixi, Boley, etc.	15	56,5	4—130	4.-
Lathes Schaublin, Waltham, Mikron Cleveland etc.	20	73 ou 80	5—200	5.-



Chuck 10 L



Chuck 12,5 L




Chuck 15 L

to be used with:	Dia of chank	Total lenght	Bored $\frac{1}{100}$ mm	Price Fr.
Lathes Lorch etc.	10	74	5—90	3.20
Lathes Lorch etc.	12,5	95,5	5—100	4.50
Lathes Lorch Wolf-Jahn etc.	15	90	5—130	5.-




CH. SCHÄUBLIN-VILLENEUVE, MALLERAY (Switzerland)

SPRING COLLETS




Type 1.

To be used with Automatic turret forming machine, Brown & Sharp, Tornos, Petermann etc. and wire feed screw machines.



Type 2.

To be used with Automatic turret forming machines and wire feed screw machines.



Type 3.

With double cone to be used with wire feed screw machines.

Warranty: All collets are made of best suiting steel, hardened and ground.

Order: Please to indicate:

1. Diameter of the shank.
2. Diameter of holes, as desired.
3. The lathe or machine with witch the collets are to be used.
4. A sketch when the collets are not illustrated in the catalogue, and especially for spring collets to be used with automatic or wire feed screw machines.

Prices: The prices are for goods taken in Malleray, packing up to add.

Discount for quantities:

5%	by order of minimum	20 pieces,
10%	" " " "	50 "
15%	" " " "	100 "